

UPT LOFT

- RIGGING PRICE LIST -

GENERAL RIGGING SERVICES

MAIN ASSEMBLE & INSPECT SPORT	50	RESERVE INSPECTION & REPACK SPORT	\$70
MAIN ASSEMBLE & INSPECT TANDEM (F111)	60	RESERVE INSPECTION & REPACK TANDEM	90
MAIN ASSEMBLE & INSPECT TANDEM (ZP)	60	RELINE TANDEM LOWER STEERING ONLY	40
MAIN INSPECTION TANDEM	35	RELINE TANDEM STEERING ONLY	50
MAIN INSPECTION SPORT	20	RELINE TANDEM F111/ZP	150
MAIN REPACK SPORT	7	WASH RIG SPORT	40
MAIN REPACK TANDEM	12	WASH RIG TANDEM	50
RESERVE ASSEMBLE, INSPECT & PACK SPORT	90	WASH RIG TANDEM WITH PASSENGER HARNESS	60
RESERVE ASSEMBLE, INSPECT & PACK TANDEM	105	LOFT LABOR RATE	50
RESERVE ASSEMBLY TANDEM	50	REPAIR ESTIMATE ONLY	(if price over \$200, waived) 25
RESERVE ASSEMBLY SPORT	30		

INSTALLATIONS / MODIFICATIONS

INCLUDES PRICE OF PARTS / MATERIALS UNLESS OTHERWISE NOTED

AAD SET UP, CYPRES ^{IF CYPRES PURCHASED FROM UPT}	\$50	SKYHOOK SIGMA	\$205
AAD SET UP, OTHER	65	SKYHOOK (Mod without RSL after 2005)	350
CYPRES MODIFICATION & INSTALLATION	100	SKYHOOK (Mod without RSL prior 2005)	400
B-12's ADDITION OR REMOVAL	150	SKYHOOK with RSL	350
BOC SET UP	50	RSL INSTALLATION RIPCORDER & LANYARD INCLUDED	125
DIVELOOP INSTALLATION	20	RSL MODIFICATION VII (w/o NEW RISERS OR CUTAWAY)	170
FREEFLY MODIFICATION	25	RSL MODIFICATION VII (w/ OVER SHOULDER VELCRO & POCKET)	153
		TANDEM MAIN CONTAINER REINFORCEMENT	105
		TANDEM SIDE FLAP REINFORCEMENT KEVLAR REPAIR	25

REPLACEMENTS

INCLUDES PRICE OF PARTS / MATERIALS UNLESS OTHERWISE NOTED

CHEST STRAP ASSEMBLY REPLACEMENT	\$70	HARNESS REPLACEMENT ^{SPORT HARNESS}	\$450
CHEST STRAP REPLACEMENT RUNNING END	60	HARNESS REPLACEMENT ^{SPORT VGH HARNESS}	450
DROGUE ATTACHMENT POINT REPLACEMENT UPPER	40	HARNESS REPLACEMENT ^{STUDENT}	500
DROGUE CENTERLINE REPLACEMENT NEW STYLE CONVERSION	165	HARNESS REPLACEMENT ^{TANDEM}	700
DROGUE CENTERLINE REPLACEMENT TUBULAR	134	LEG PAD REPLACEMENT SPORT (SPACER FOAM)	95
DROGUE POUCH REPLACEMENT	150	LEG PAD REPLACEMENT SPORT	75
CENTER FLAP REPLACEMENT SIGMA	150	LEG PAD REPLACEMENT STUDENT	90
CENTER FLAP REPLACEMENT NO PIPING VECTOR III	170	LEG PAD REPLACEMENT TANDEM	100
MAIN CLOSING FLAP FREESTYLE ELASTIC	20	LEG PAD REPLACEMENT TANDEM PASSENGER HARNESS	95
MAIN CLOSING FLAP TONGUE INSTALLATION	15	MAIN LOOP ANCHOR RELOCATION (TO #1 FLAP)	25
MAIN PIN FLAP CLOSING TONGUE REPLACEMENT VII	35	MAIN LOOP ANCHOR w/o CYPRES POCKET REPLACEMENT VII	15
MAIN PIN FLAP REPLACEMENT VECTOR II	60	MAIN OR RESERVE CONTAINER REPLACEMENT VII	400
MAIN SIDE FLAP (#6) REPLACEMENT VECTOR II	105	MAIN OR RESERVE CONTAINER REPLACEMENT VIII	400
RESERVE PIN FLAP REPLACEMENT VECTOR II OR III	65	ROL POCKET REPLACEMENT	60
GROMMET REPLACEMENT (10)	35		

ALL PRICE ESTIMATES ARE SUBJECT TO CHANGE BASED ON RIGGERS EVALUATION OF WORK TO BE PERFORMED. PRICE CHANGES CAN BE INCURRED BY ADDITIONAL LABOR HOURS, SERVICES, PARTS AND/OR MATERIALS. ALL ADDITIONAL SERVICES MUST BE APPROVED BY CUSTOMER PRIOR TO WORK BEING COMPLETED. PRICES SUBJECT TO CHANGE DUE TO FOREIGN CURRENCY RATES. PRICES AND SPECIFICATIONS ARE SUBJECT TO CHANGE WITHOUT NOTICE.

¹DOES NOT INCLUDE PRICE OF AAD. ²DOES NOT INCLUDE STAINLESS STEEL HARDWARE.

